

Product Data Sheet

IN/OUT Thermometer Double Display

Reference 91000-041/B

Specifications

- -50+70°C / -58+158°F
- Resolution : 0.1°
- Accuracy: $\pm 1^{\circ}\text{C}$ / $\pm 2^{\circ}\text{F}$
- Cable : 200 cm
- MAX/MIN
- IN/OUT
- Alarm
- AAA battery
- In BIOTEMP blister



Instructions

Insert the battery to start the unit. Press [°C/°F] once to select the measure unit.

MAX/MIN FUNCTION

Pressing [MAX/MIN] once will display the maximum temperature. Pressing [MAX/MIN] once more will display the minimum temperature.

Pressing [MAX/MIN] once again to display the ambient temperature. Pressing [MAX/MIN] again for 1 second to clear the memory.

ALARM FUNCTION

Press [ALE] to start the alarm function, you will see ALE (ON) on the screen.

Press [ALE] again, you will see ALE (OFF) on the screen.

Without imputing any new setting within 2 seconds, the device will reset automatically to the initial temperature.

Hold down [ALE] for 3 seconds: the alarm for the outside temperature will flash,

press [°C/°F] to set the default OUT temperature (-1°C/30°F).

Press [ALE] again and then [°C/°F] to set the default IN temperature (5°C/39.2°F).

Press [ALE] to validate the settings.

If the temperature value is out of the set limit then the alarm will sound 5 times every minute until the temperature is within the set limit.

Alla France

Z.I. du Bompas - 13, rue du Bompas - Chemillé - 49120 Chemillé-en-Anjou - FRANCE
Tél. + 33 (0)2 41 30 55 08 - Fax +33 (0)2 41 30 34 67

www.allafrance.com


France